

COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT AATCC 16	RUBBING AATCC 8		WASHING AATCC61				PERSPIRATION AATCC 15		SALT WATER AATCC 106		CHLORINE AATCC 162
		Dry	Wet	C.C	S.Pl	S.Pa	S.Co	C.C	S.Pl	C.C	S.Pl	C.C
WHITE	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
BLACK	3	3-4	2-3	4	4	4	4	4	4	4	3	4
SKINTONE	3	3-4	2-3	4	4	4	4	4	4	4	3	4

C.C: Colour Change.
S.Co: Staining on Cotton.
S.Pa: Staining on Nylon.
S.Pl: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		