

COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT ISO 105 B02	RUBBING ISO 105 X12		WASHING 40oc ISO 105 C06	WATER ISO 105 E01	PERSPIRATION ISO 105 E04		CHLORINATED WATER ISO 105-E03	SALT WATER ISO 102-B02
	C.C	Dry	Wet	C.C	C.C	ACID	ALKALINE	C.C	C.C
BLACK	4	4	4	4	4	4	4	3	4

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.Pl: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		