

COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	WASHING AS2001.4.15 TEST J2				WATER AS2001.4-E01				PERSPIRATION AS2001.4-E04				RUBBING AS2001.4.3		LIGHT AS2001.4.21 60HRS
	C.C	S.PI	S.Pa	S.Co	C.C	S.PI	S.Pa	S.Co	C.C	S.PI	S.Pa	S.Co	DRY	WET	C.C
BLACK	4-5	4	4	4	4-5	3-4	3	4	4-5	3-4	3	4	4-5	4	5-6
SHADOW	4-5	4	3	4	4-5	4	3-4	4	4-5	4	3-4	4	4-5	4	5-6

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.PI: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		