

COLOUR FASTNESS

Combination of colours is not recommended when the fastness values are lower than 4-5. When splicing colours with White we also recommend using a complimenting Polyester base.

COLOUR	LIGHT ISO 105 B02	WASHING ISO 105 C06 B25			SEA WATER ISO 105 E02			PERSPIRATION ISO 105 E04			CHLORINE ISO 105 E03		
	C.C	C.C	S.Pa	S.Pl	C.C	S.Pa	S.Pl	C.C	S.Pa	S.Pl	C.C	S.Pa	S.Pl
WHITE	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	
BLACK	4	4	4	4	4	4	4	4	4	4-5	4	4	4
SKINTONE	4	4	4-5	4	4	4-5	4	4	4-5	4	4	4-5	4

- C.C: Colour Change.
- S.Co: Staining on Cotton.
- S.Pa: Staining on Nylon.
- S.Pl: Staining on Polyester.

COLOUR FASTNESS ASSESSMENT VALUES			
LIGHT	ASSESSMENTS	OTHER TESTS	ASSESSMENTS
1	Very Weak	1	Weak
2	Weak	2	Limited
3	Moderate	3	Fair
4	Fair	4	Good
5	Good	5	Very Good
6	Very Good		
7	Optimal		
8	Exceptional		